## **Test Report**

Club Fleet - Sacramento: ID 9340

Company:

City: ZIP: Address: E-mail: Username: Firmware Version: App Version:	Gold River 95670 2381 Gold River Rd Suite B sacfleet@norcal.aaa.com Brian Pepper GA11 2.1.5338
Replace soon	
Test Parameters Battery Type: Test Voltage: Test Standard: Reference Value: Temperature: Date/Time:	WET 12V CCA 500 CCA WET 19°C 12/18/16 1:20 PM
State of Charge Charge Status: Voltage:	Normal 56.0% 12.14V
State of Health State of Health:  Measured Value: Internal Resistance: Conductance:	Warning 24.0% 367 CCA 7.78mohm 129MHO
Cranking Health Cranking Health: Cranking Voltage:	Pass 74.0% 8.34V
Charging System Charging Health: Charging Voltage: Ripple Test: Diode Ripple:	Low Voltage, Check Charging System 12.39V Pass 1711
Battery Information Battery UPC: Battery Brand: Battery Model: BCI/JIS Size: Manufacture Date: Installation Date: Battery ID: Owner: Service Number:	758589415189 Interstate 85
Vehicle Information VIN: Vehicle Make:	Honda

Vehicle Model: Vehicle Year: Vehicle Registration: Civic 2012